

# AGILENT TECHNOLOGIES NETWORK ANALYZER PRINTER COMPATIBILITY GUIDE\*\* (Page 1 of 2)

Compatibility Key: Blank-Indicates not tested Yes-Indicates tested and works No-Indicates tested and does not work

Last Updated: 12/26/2000

Printer Color Code: B = Black & White Only C = Color CP = Color Capable - (B & W std.)		G= GPIB S = Serial P = Parallel U = USB	E5100A/B	4395A 4396B	8711/A/B/C (1) 8712/13B/C (1) 8714B/C (1) 8712ET/ES 8714ET/ES	8753D/E/ET/ES 8719D/ET/ES 8720D/ET/ES 8722D/ET/ES	PNA Series E8356A E8357A E8358A	8757D/E	8751A	8752A/B	8752C	8753C	8719A/C 8720A/B/C 8722A/C
Interface=			P	P	G/S/P	G/S/P	U/P	G*	G*	G*	G*	G*	G*
<b>HP DeskJets</b>													
DeskJet	B (1)	S/P				Yes		Yes		Yes	Yes	Yes	Yes
DeskJet Plus	B (1)	S/P			Yes	Yes		Yes		Yes	Yes	Yes	Yes
400L (C2642D)	CP	P			Yes	Yes		Yes (2)			Yes	Yes (2,3)	Yes (2,3)
500 (C2106A)	B (1)	S/P			Yes	Yes		Yes	Yes	Yes	Yes	Yes	Yes
500C (C2114A)	CP (1)	S/P			Yes	Yes		Yes (2)	Yes (2)	Yes (2)	Yes	Yes (2)	Yes (2)
520 (C2170A)	B (1)	P			Yes	Yes		Yes		Yes	Yes	Yes	Yes
540 (C2162A)	CP (1)	P			Yes	Yes		Yes (2,5)		Yes (2,5)	Yes	Yes (2,5)	Yes (2,5)
550C (C2121A)	C (1)	S/P			Yes	Yes		Yes (2)		Yes (2)	Yes	Yes (2)	Yes (2)
560C (C2168A)	C (1)	P			Yes	Yes		Yes (2)		Yes (2)	Yes	Yes (2)	Yes (2)
600 (C2184A)	CP (1)	P			Yes	Yes		Yes (2)			Yes	Yes (2,3)	Yes (2,3)
660C (C2164A)	C (1)	P		Yes (10)	Yes	Yes		Yes (2)			Yes	Yes (2,3)	Yes (2,3)
672C (C5886A)	C (1)	P	Yes (2)	Yes (10)	Yes	Yes		Yes (2)	Yes (2)		Yes	Yes (3,4)	Yes (3,4)
680C (C4549A)	C (1)	P						Yes (2)					
682C (C4567A)	C (1)	P			Yes	Yes						Yes	
690C (C4562A)	C (1)	P		Yes (10)	Yes	Yes		Yes (2,3)	Yes (2)		Yes	Yes (2,3)	Yes (2,3)
694C (C4608A)	C (1)	P	Yes (2)	Yes (10)	Yes	Yes		Yes (2)			Yes	Yes (6)	Yes (6)
720C (C5870A)	C	P	No	No					No				
722C (C5871A)	C (1)	P			No	No		No			No	No	No
820C (C4531A)	C (1)	P			No	No		No		No	No	No	No
840C (C6414A)	C	U/P			Yes	Yes	Yes	Yes (2)			Yes	Yes	
850C (C2145A)	C (1)	P		Yes (10)	Yes	Yes		Yes (2,5)			Yes	Yes (2,3,5)	Yes (2,3)
870C (C4565A)	C (1)	P		Yes (10)	Yes(9)	Yes		Yes (2)			Yes	Yes (3,4,6)	Yes (3,4,6)
880C (C6409A)	C (1)	P	Yes (2,9)	Yes (10)	Yes	Yes		Yes (2)	Yes (2)				Yes
890C (C5877A)	C (1)	P			Yes(3,9)	Yes		Yes (2)			Yes	Yes (3,4,6)	Yes (3,4,6)
895C (C6410A)	C	P	Yes (2,9)	Yes (10)	Yes	Yes		No	Yes (2)		No	No	Yes (3,4)
930C (C6427A)	C	U/P	Yes (2,9)	Yes (10, 12 or 13)	Yes	Yes	Yes	Yes (2)			Yes	Yes	
970C (C6429A)	C	P	Yes (2)	Yes (8)	Yes	Yes		No			Yes	Yes	Yes
1120C (C2680A)	C (1)	P			Yes	Yes		Yes (2,3)			Yes	Yes	Yes (3)
1200C (C1676A)	C (1)	P	Yes (2)	Yes (10)	Yes	Yes		Yes (2)	Yes (2)	Yes (2)	Yes	Yes (2)	Yes (2)
1600C (C3540A)	C (1)	P			Yes	Yes		Yes (2)			Yes	Yes (2,3)	Yes (2,3)

\* NOTE: For Instruments with GP-IB interfaces only, an Intelligent Interfaces Inc. GP-IB to parallel converter (Micro Print 45CH) is

REQUIRED to operate printers with a parallel interface.

URL: [www.intelligentinterfaces.com](http://www.intelligentinterfaces.com)

- |  |   |
|--|---|
| <p>(1) -Discontinued.</p> <p>(2) -Works in Black and White Mode only.</p> <p>(3) -Requires manual form-feed of paper or press reset on converter.</p> <p>(4) -May be slow, but will print. Colors may be wrong. Use color or color reversal mode.</p> <p>(5) -Printout is 33% smaller than normal.</p> <p>(6) -Prints the letter "A" at the top left corner.</p> <p>(7) -Requires Windows driver. Epson ESC/P 2 printer language is not supported.</p> | <p>(8) -Analyzer may require preset after is connected</p> <p>(9) -Applies only to E5100A/B with rev.3.20 or later</p> <p>(10) -Does not work with Variable Color mode</p> <p>(11) -GPIB printers do not work satisfactorily with 871XES/ET rev.E.06.00 or later</p> <p>(12) - Test equipment must be powered On or Preset after printer is connected and powered on.</p> <p>(13) - When power-on switch of printer filcks, you will be able to print screen image by pushing following keys:<br/>1) Push the "COPY ABORT" key of instruments. 2) Press "Print Standard" key of instrument.</p> |
|--|---|

\*\*This guide assumes the instrument contains the latest available firmware as of September 2000. To achieve compatibility may require a firmware upgrade.

## AGILENT TECHNOLOGIES NETWORK ANALYZER PRINTER COMPATIBILITY GUIDE\*\* (Page 2 of 2)

Compatibility Key: Blank-Indicates not tested Yes-Indicates tested and works No-Indicates tested and does not work

Last Updated: 12/26/2000

Printer Color Code: B = Black & White Only C = Color CP = Color Capable - (B & W std.)			G = GPIB S = Serial P = Parallel U = USB	E5100A/B	4395A 4396B	8711/A/B/C (1) 8712/13B/C (1) 8714B/C (1) 8712ET/ES 8714ET/ES	8753D/E/ET/ES 8719D/ET/ES 8720D/ET/ES 8722D/ET/ES	PNA Series E8356A E8357A E8358A	8757D/E	8751A	8752A/B	8752C	8753C	8719A/C 8720A/B/C 8722A/C
Interface=			P	P	G/S/P	G/S/P	U/P	U/P	G*	G*	G*	G*	G*	G*
<b>HP Portable DeskJets</b>														
DeskJet Portable	B (1)	P			Yes	Yes			Yes		Yes	Yes	Yes	Yes
310 (C2621A)	CP (1)	P			Yes	Yes			Yes (2)		Yes (2)	Yes	Yes (2)	Yes (2)
320 (C2634A)	CP (1)	P			Yes	Yes			Yes (2)		Yes (2)	Yes	Yes (2)	Yes (2)
340 (C2655A)	CP	P			Yes	Yes			Yes (2)			Yes	Yes (2,3)	Yes (2,3)
<b>HP InkJets</b>														
PaintJet	C (1)	G/S/P			Yes (11)	Yes			Yes		Yes	Yes	Yes	Yes
QuietJet	B (1)	G/S/P			Yes (11)	Yes			Yes		Yes	Yes	Yes	Yes
ThinkJet	B (1)	G/S/P			Yes (11)	Yes			Yes		Yes	Yes	Yes	Yes
<b>HP LaserJets</b>														
III	B (1)	S/P			Yes	Yes			Yes		Yes	Yes	Yes	Yes
4 (C2001A)	B (1)	S/P			Yes	Yes			Yes		Yes	Yes	Yes	Yes
4L (C2003A)	B (1)	P			Yes	Yes			No		No	Yes	No	No
4P (C2005A)	B (1)	S/P			Yes	Yes			Yes		Yes	Yes	Yes	Yes
4 Plus (C2037A)	B (1)	S/P			Yes									
5L (C3941A)	B (1)	P			Yes	Yes			Yes			Yes	Yes	Yes
5N (C3952A)	B (1)	S/P			Yes	Yes			Yes			Yes	Yes	Yes
5P (C3150A)	B (1)	P			Yes	Yes			Yes			Yes	Yes (3)	Yes (3)
6P (C3150A)	B (1)	P			Yes	Yes			Yes			Yes	Yes	Yes
1100 (C4224A)	B	P			Yes	Yes			Yes			Yes	Yes	Yes
<b>Epson Printers</b>														
MX-80	B (1)					No			No		No	No	No	No
Stylus Color	C (7)	P			No	No			No		No	No	No	No
LQ-570	B (1)	S/P			Yes	Yes			No		No	Yes	No	No

\* NOTE: For Instruments with GP-IB interfaces only, an Intelligent Interfaces Inc. GP-IB to parallel converter (Micro Print 45CH) is

REQUIRED to operate printers with a parallel interface.

URL: [www.intelligentinterfaces.com](http://www.intelligentinterfaces.com)

- |  |   |
|--|---|
| <p>(1) -Discontinued.</p> <p>(2) -Works in Black and White Mode only.</p> <p>(3) -Requires manual form-feed of paper or press reset on converter.</p> <p>(4) -May be slow, but will print. Colors may be wrong. Use color or color reversal mode.</p> <p>(5) -Printout is 33% smaller than normal.</p> <p>(6) -Prints the letter "A" at the top left corner.</p> <p>(7) -Requires Windows driver. Epson ESC/P 2 printer language is not supported.</p> | <p>(8) -Analyzer may require preset after is connected</p> <p>(9) -Applies only to E5100A/B with rev.3.20 or later</p> <p>(10) -Does not work with Variable Color mode</p> <p>(11) -GPIB printers do not work satisfactorily with 871XES/ET rev.E.06.00 or later</p> <p>(12) - Test equipment must be powered On or Preset after printer is connected and powered on.</p> <p>(13) - When power-on switch of printer filcks, you will be able to print screen image by pushing following keys:<br/>1) Push the "COPY ABORT" key of instruments. 2) Press "Print Standard" key of instrument.</p> |
|--|---|

\*\*This guide assumes the instrument contains the latest available firmware as of September 2000. To achieve compatibility may require a firmware upgrade.